BLOCK MANAGEMENT LTD
PROFESSIONAL PROPERTY MANAGEMENT

Site Inspection Record

Company Name: The Ropeyard (Wootton Bassett) Management Company Limited

Inspector Name: W. Kremer

Inspection Date: 05 October 2026

Purpose

This site inspection record is used when undertaking regular site inspections and is solely for the purpose of recording and monitoring the common (communal) parts on behalf of the above company.

What Is Included

The below report comments on the general condition of the interior and exterior communal parts (where applicable) as they were found at the time of this inspection.



Please note: This inspection is carried out visually by the property manager or a competent person instructed by the property manager and should not be used for any other purpose than to comment and record the general state and condition of the common (communal) parts that are inspected during a routine site visit. Where further investigation, testing or remedial work is required, a competent person is instructed by the property manager.

BLOCK MANAGEMENT LTD



PROFESSIONAL PROPERTY MANAGEMENT

Internal Inspection	Acceptable	Not Acceptable	N/A	Comments	Action
Entrances (Main doors)	✔			The doors open and closes correctly.	None
Hallway (Communal Lobbies and Stairs)	✔			Hallway and stairs are clean and tidy.	None
Lighting (Standard and Emergency Lighting)	✔			The lights are working correctly, emergency lights have also been checked and are working perfectly.	None
Internal Doors (Compartment Doors)			✔		None
Cupboard Doors (Electrical Cupboard Doors)	✔			Electrical cupboard door close and open correctly.	None
Windows (Communal Windows)	✔			The window close and open correctly.	None
Signage (Communal Notices)	✔			The information board is displayed in a visible location and contains all the information regarding the building.	None
Additional Comments					None

BLOCK MANAGEMENT LTD

PROFESSIONAL PROPERTY MANAGEMENT

External Inspection	Acceptable	Not Acceptable	N/A	Comments	Action
Exterior Structure (The Building)	✔			The exterior structure of the building is in good condition with no visible issues.	None
Guttering (Gutters and Fascia)	✔			The guttering appeared to be in good visual condition.	None
Roofing (Tiles and Cladding)	✔			The roof was inspected from ground level and appeared to be in good visual condition.	None
Communal Grounds (Gardens and Common Areas)	✔			The communal grounds, garden and common areas are well maintained by the gardens, free of litter.	None
Bin Store (Waste Disposal Areas)	✔			Each flat has their own assigned bin.	None
Car Park (Vehicle Parking)	✔			The car park is well-maintained.	None
Bike Store (Bicycle Areas)			✔		None
Additional Comments					None

Entrances (Main Doors)	Hallway (Communal Lobbies and Stairs)	Lighting (Standard and Emergency Lights)	Internal Doors (Compartment Doors)
			
Cupboard Doors (Electrical Cupboard Doors)	**Windows (Communal Windows)**	**Signage (Communal Notices)**	**Additional Photos**
			

Exterior Structure (The Building)	Guttering (Gutters and Fascia)	Roofing (Tiles and Cladding)	Communal Grounds (Gardens and Common Areas)
			
Bin Store (Waste Disposal Area)	**Car Park (Vehicle Parking)**	**Bike Store (Bicycle Areas)**	**Additional Photos**
			